BOREWELL CERTIFICATE

Name of the Work:	Drilling of Bore wells providing pump motor and Servicing at Model Colony in Dasarahalli ward No 15
Job No:	015-14-000002
Work order No:	EE/DD/WO/304/13-14 DATE 26.02.14
BR No:	327/14-15 DATE 16.7.14

The Inspection team deployed for this purpose has opined that generally the work executed is satisfactory (in the report available in the file. As such, compliance of Geological survey report, Yield test report and water probability tests report at this stage is not feasible, since this work was executed one year's back.

25/5

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike